

**ASBESTOS-CONTAINING MATERIALS  
REINSPECTION REPORT & MANAGEMENT PLAN UPDATE**

**FRED S. ESHELMAN ELEMENTARY SCHOOL  
E8711-05B**

**TABLE OF CONTENTS**

<u>SECTION 1 - GENERAL</u>	<u>PAGE</u>
A. Table of Contents	1A1
 <u>SECTION 4</u>	
A. Reinspection	4A1 to 4A8
Date of Inspection/Inspector	4A1
Accreditation Certificate	4A3
Homogeneous Areas	4A7
B. Assessments	4B1 to 4B12
Assessment Procedure/Inspector	4B1
Assessments	4B3
Field Assessment Forms	4B5
 <u>SECTION 6</u>	
A. Response Actions	6A1 to 6A8
Response Actions Recommended	6A1
Selected Response Actions	6A5
B. Specific Location of Asbestos Materials	6B1
List of Asbestos-Containing Materials	6B1
C. Follow-Up to Response Actions	6C1 to 6C3
Periodic Surveillance Schedule	6C1
Specific O&M Procedures	6C2
 <u>SECTION 7</u>	
B. Resource Evaluation	7B1 to 7B2
Estimated Cost of Recommended Response Actions	7B1
Estimated Cost of Selected Response Actions	7B2

## REINSPECTION SUMMARY

A reinspection for Asbestos-Containing Materials was performed at the Fred S. Eshelman Elementary School, under jurisdiction of the Penn Manor School District, by Environmental Hazards Consulting, Inc., One Penn Square, Lancaster, Pennsylvania 17602, on May 13, 1994.

The inspection was performed in accordance with the standards of 40 CFR, Part 763, Subpart E, the AHERA Regulations, for the purpose of the required three-year reinspection.

The results of the inspection are presented on the following pages.

In some instances, asbestos-containing materials concealed by the existing construction and finish materials and not indicated in any construction or renovation documentation, cannot be detected without significant disturbance or demolition of the construction or finish. Roofing materials were not sampled as part of the survey but may contain asbestos. Therefore it is recommended that the LEA utilize an accredited inspector prior to demolition or renovation work to further investigate, and during renovation or demolition work should suspect materials be uncovered, for any concealed materials not accessible during this survey.

Certain materials obvious to the inspector as typically containing asbestos and materials previously sampled and confirmed as asbestos-containing by others, were assumed to be ACBM and are listed under "Homogeneous Areas".

Inspector:

Name: Kenneth W. Houseman

Kenneth W. Houseman  
Signature

May 26, 1994  
Date

## REINSPECTION SUMMARY

A reinspection for Asbestos-Containing Materials was performed at the Fred S. Eshelman Elementary School, under jurisdiction of the Penn Manor School District, by Environmental Hazards Consulting, Inc., One Penn Square, Lancaster, Pennsylvania 17602, on November 21, 1994.

The inspection was performed in accordance with the standards of 40 CFR, Part 763, Subpart E, the AHERA Regulations, for the purpose of the required three-year reinspection.

The results of the inspection are presented on the following pages.

In some instances, asbestos-containing materials concealed by the existing construction and finish materials and not indicated in any construction or renovation documentation, cannot be detected without significant disturbance or demolition of the construction or finish. Roofing materials were not sampled as part of the survey but may contain asbestos. Therefore it is recommended that the LEA utilize an accredited inspector prior to demolition or renovation work to further investigate, and during renovation or demolition work should suspect materials be uncovered, for any concealed materials not accessible during this survey.

Certain materials obvious to the inspector as typically containing asbestos and materials previously sampled and confirmed as asbestos-containing by others, were assumed to be ACBM and are listed under "Homogeneous Areas".

Inspector:


Name: Don Farrell, II

Signature



11-21-94

Date



NOT APPROVED FOR WORK IN MARYLAND SCHOOLS



BIOSPHERICS<sup>®</sup> INCORPORATED  
12051 Indian Creek Court  
Dolaville, Maryland 20705  
(301) 419-3900

*This is to certify that*

Kenneth W. Houseman, sr.

*has successfully completed  
an EPA approved course for  
Building Inspectors (Refresher)*

*entitled*

Asbestos Hazards, Abatement and Protection  
*given*  
November 12, 1993

*Karen M. Malony*  
Instructor  
*Rachel Riley*  
Course Director

93-11-12-22  
Certification Number  
November 12, 1994  
Certification Expires

THIS TRAINEE HAS SUCCESSFULLY PASSED OUR EXAMINATION.



ASBESTOS CERTIFICATION  
DEPARTMENT OF LABOR & INDUSTRY  
SEX HEIGHT EYES BIRTHDATE  
M 6'02 GRN 05/29/60  
EXPIRATION DATE ISSUE DATE  
12/08/94 01/11/94  
CERTIFICATION NUMBER CLASSES  
002247 05

DONALD L FARRELL II  
1005 FOUNTAIN AVE  
LANCASTER PA 17601

*Donald Farrell*

PENNSYLVANIA ASBESTOS OCCUPATIONS CERTIFICATION  
PHOTO ID CARD

This certification has been issued in accordance with the Asbestos Occupations Accreditation and Certification Act, Act 194-1980. Fraudulently altering, exhibiting or loaning this certification is a serious crime. Violators are subject to prosecution, fine, and cancellation of their Asbestos Occupations Certification card.

CLASSES OF CERTIFICATION

- |  |                     |                       |
|--|---------------------|-----------------------|
| 1. Worker  | 2. Project Designer | 5. Management Planner |
| 2. Supervisor  | 4. Inspector        | 6. Contractor         |
| * Within 15 days of change of name and/or address, you are required to notify the Bureau in writing. |                     |                       |

- \* If this certification is found, mail to:

Pennsylvania Department of Labor and Industry  
Bureau of Occupational and Industrial Safety  
P.O. Box 3465  
Harrisburg, PA 17105-3465

**Center for Environmental and  
Occupational Training, Inc.**

814 East Pittsburgh Plaza • East Pittsburgh, Pennsylvania 15112

This is to certify that

DONALD L. FARRELL, II

has successfully completed the following course  
with a passing score of 70 percent or better.

**ASBESTOS BUILDING INSPECTOR RECERTIFICATION**



**266-39-4686**

Certification Number

**DECEMBER 7, 1993**

Course Dates

**DECEMBER 7, 1993**

Exam Date

**DECEMBER 8, 1994**

Expiration Date

*John H. Lange*

John H. Lange  
Director of Training

*D. S. Ginsburg*

D. S. Ginsburg, D.M.D., M.H.A.  
Course Administrator

## HOMOGENEOUS AREAS

ASBESTOS CONTENT: C - Chrysotile, A - Amosite, CR - Crocidolite, TR - Tremolite, AC - Actinolite  
 ASMD - Assumed, ND - None Detected

Homogeneous Area No.	Material	Location	Approx. Amount	Material Classification	Friability	Asbestos Content	Sample No(s).
01	Breeching Insulation	Boiler Room	280 S.F.	Thermal Systems Insulation	Friable	55% *Sampled by Others	
02	Pipe Fitting Insulation	Throughout Original (1958) Building	250 Fittings	Thermal Systems Insulation	Friable	15% 30% *Sampled by Others	
03	Emergency Generator Exhaust Pipe (Transite)	Boiler Room	28 L.F.	Miscellaneous Material	Non-Friable	20% 30% *Sampled by Others	
04	Quarry Floor Tile	Classrooms	15,000 S.F.	Miscellaneous Material	Non-Friable	5% *Sampled by Others	
05	Transite Boards	Exterior Soffits	3,000 S.F.	Miscellaneous Material	Non-Friable	ASMD *Assumed by Others	4A7

008711 Penn Manor School District

BLDG. NO: 04 BUILDING NAME: Fred S. Eshelman Elem. School

HOMOGENEOUS AREAS [CONTINUED]

ASBESTOS CONTENT: C - Chrysotile, A - Amosite, CR - Crocidolite, TR - Tremolite, AC - Actinolite  
ASMD - Assumed, ND - None Detected

Home. Area No.	Material	Location	Approx. Amount	Material Classification	Friability	Asbestos Content	Sample No(s).
06	Pink Terrazzo Flooring	Corridors Throughout Building	3,000 S.F.	Miscellaneous Material	Non-Friable	ASMD	-

## ASSESSMENT PROCEDURE/INSPECTOR

(Page 1 of 2)

### Assessment Procedure:

Assessments were performed of the Friable ACBM in accordance with Section 768.88 of 40 CFR, Part 768, Subpart E. Field assessment forms were completed as part of the assessment evaluation and are hereinafter included as reference standards for future inspection by the LEA. The factors considered and the reason for the assessment classification are contained on these forms.

For the purposes of overall information organization, all suspect and confirmed ACBM materials have been assigned assessment numbers.

The materials were assessed in regard to existing condition, damage potential and exposure potential. Each material was classified into each of the following three assessment criteria categories:

#### Existing Condition:

1. Significantly Damaged
2. Damaged
3. No Damage

#### Potential for Damage:

1. Potential for Significant Damage
2. Potential for Damage
3. Low Potential for Damage

#### Potential for Exposure

1. Potential for Significant Exposure
2. Potential for Exposure
3. Low Potential for Exposure

Each asbestos-containing material was then classified into one of the following categories established by the AHERA Regulations.

1. Damaged or significantly damaged thermal systems insulation.
2. Damaged friable surfacing ACM.
3. Significantly damaged friable surfacing ACM.
4. Damaged or significantly damaged friable miscellaneous ACM.
5. ACBM with potential for damage.

**ASSESSMENT PROCEDURE/INSPECTOR**

(Page 2 of 2)

6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.
8. Non-friable ACBM

Inspector:

Name: Don Farrell, II

Signature



Date

11-21-94

008711 Penn Manor School District

BLDG. NO: 04 BUILDING NAME: Fred S. Eshelman Elem. School

**ASSESSMENT REPORT**

**Assessment Criteria:**

Homo. Area No.	Asmt No.	Functional Space(s) and Material	Approx. Amount	Existing Damage		Exposure Potential	AHERA Class.
				Damage Potential	Damage Potential		
01	A	Boiler Room Breeching Insulation	280 S.F.	2 Damage	2 Potential	2 Potential	01
02	A	Boiler Room Pipe Fitting Insulation	90 Fittings	1 No Damage	2 Potential	2 Potential	05
02	B	Orig. (1958) Entire Building, Above Suspended Ceilings Pipe Fitting Insulation	156 Fittings	1 No Damage	2 Potential	2 Potential	05
02	C	Kitchen (Near Serving Line) Space Heater Pipe Fitting Insulation	4 Fittings	1 No Damage	2 Potential	3 Significant Potential	05
03	A	Boiler Room Emergency Generator Exhaust Pipe (Transite)	28 L.F.	1 No Damage	2 Potential	2 Potential	08

008711 Penn Manor School District

BLDG. NO: 04 BUILDING NAME: Fred S. Eshelman Elem. School

ASSESSMENT REPORT [CONTINUED]

Assessment Criteria:

Hono. Area No.	Assmt. No.	Functional Space(s) and Material.	Approx. Amount	Existing Damage		Exposure Potential	AIHERA Class.
				Damage Potential	Potential		
04	A	Classrooms 9"x9" Floor Tile	15,000 S.F.	1 No Damage	2 Potential	3 Significant Potential	08
05	A	Exterior Soffits Transite Boards	3,000 S.F.	1 No Damage	2 Potential	3 Significant Potential	08
06	A	Corridors Throughout Building Pink Terrazzo Flooring	3,000 S.F.	1 No Damage	1 Low Potential	3 Significant Potential	08

Project No. <u>E911/ - / - OSB</u>	Client: <u>PENN MANOR SCH. DISTRICT.</u>	Homog Area: <u>01</u>
clnt div fac proj Building: <u>FRED S. ESHELMAN ELEMENTARY.</u>		No. <u>04</u>
Assessment: <u>A</u>		

Functional Space(s): <u>BOILER ROOM.</u>	Material: <u>BRECHING INSULATION.</u>	Amount: <u>280</u> Sq.Ft. _____ Lin.Ft.
--	---------------------------------------	---

Friability: <input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non-Friable	Type: <input type="checkbox"/> Surfacing <input checked="" type="checkbox"/> Thermal Insulation <input type="checkbox"/> Misc.	Asbestos Content: _____
--	--	-------------------------

<b>EXISTING DAMAGE</b>		Rating: <input type="checkbox"/> Significantly Damaged <input checked="" type="checkbox"/> Damaged <input type="checkbox"/> No Damage	
Physical Damage:	Water Damage:	Deterioration:	Damage Extent:
<input type="checkbox"/> Significant >10%	<input type="checkbox"/> Significant >10%	<input type="checkbox"/> Significant >10%	<input checked="" type="checkbox"/> Localized
<input checked="" type="checkbox"/> Damaged <10%	<input type="checkbox"/> Damaged <10%	<input checked="" type="checkbox"/> Deteriorated <10%	<input type="checkbox"/> Distributed
<input type="checkbox"/> No Damage	<input checked="" type="checkbox"/> No Damage	<input type="checkbox"/> No Deterioration	<input type="checkbox"/> Both
Remarks: <u>MINIMAL DAMAGE AT BOTTOM.</u>			

<b>DAMAGE POTENTIAL</b>		Rating: <input type="checkbox"/> Significant Potential <input checked="" type="checkbox"/> Potential <input type="checkbox"/> Low Potential	
Fiber Release Deterrent:	<input type="checkbox"/> None <input type="checkbox"/> Sealed Enclosure <input checked="" type="checkbox"/> Barrier <input type="checkbox"/> Encapsulant		
Description: <u>COVERED &amp; PAINTED.</u>			

Accessibility:	<input checked="" type="checkbox"/> Within Normal Reach <input type="checkbox"/> Barely Reachable <input type="checkbox"/> Not Reachable		
Functional Space Activity: <u>BOILER ROOM.</u>			

Proximity To Items Requiring Maintenance/Repair:	<u>- 0 -</u> Feet		
Type Of Maintenance/Repair: <u>BOILER / FUEL REPAIR / MAINT.</u>			

Subject To Moisture Damage:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Source:	<input checked="" type="checkbox"/> Piping <input checked="" type="checkbox"/> Roof Leak <input type="checkbox"/> Sprinkler <input type="checkbox"/> Other
Description: <u>NO LEAKS NOTED.</u>			

Ventilation:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> Mechanical <input type="checkbox"/> Intake	Movement:	<input type="checkbox"/> High <input type="checkbox"/> Moderate
	<input type="checkbox"/> No <input checked="" type="checkbox"/> Natural <input type="checkbox"/> Exhaust	<input type="checkbox"/> Low <input checked="" type="checkbox"/> Variable	
Description: <u>NATURAL AIR MOVEMENT.</u>			
Potential For Air Erosion: <input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low			

Vibration - Potential For Fiber Release:	<input type="checkbox"/> High <input checked="" type="checkbox"/> Moderate <input type="checkbox"/> Low		
Description: <u>NOTICABLE VIBRATION AFFECTING MINIMALLY DAMAGED ACM.</u>			

<b>EXPOSURE POTENTIAL</b>		Rating: <input type="checkbox"/> Significant Potential <input checked="" type="checkbox"/> Potential <input type="checkbox"/> Low Potential	
Accessibility:	<input type="checkbox"/> General Population <input type="checkbox"/> Tenants <input type="checkbox"/> Operations <input checked="" type="checkbox"/> Routine Maintenance <input checked="" type="checkbox"/> Repair		
Remarks: <u>AREA ACCESSED FOR MAINT + REPAIR ONLY.</u>			

Dust/Debris Present:	<input type="checkbox"/> Significant <input type="checkbox"/> Moderate <input type="checkbox"/> Slight <input checked="" type="checkbox"/> None		
----------------------	---	--	--

Fiber Transport:	<input checked="" type="checkbox"/> None <input type="checkbox"/> Air Plenum/Chase <input type="checkbox"/> Ductwork <input type="checkbox"/> Mechanical Shaft <input type="checkbox"/> Elevator/Dumbwaiter <input type="checkbox"/> Other		
Description: <u>NONE.</u>			

Photographs:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	No's: _____	AHERA Classification Number: <u>1</u>
--------------	---	-------------	---------------------------------------

ASSESSMENT: <u>2001</u>	RESPONSE: <u>R11</u>	PRIORITY: <u>P2</u>	PERIODIC SURVEILLANCE: <u>51</u>	oH: <u>1F</u> / MN: _____ / CP: _____
-------------------------	----------------------	---------------------	----------------------------------	---------------------------------------

Inspector: <u>KENNETH C. Hauseman</u>	Certification No.: <u>93-11-12-23</u>
---------------------------------------	---------------------------------------

Signature: <u>Kenneth C. Hauseman</u>	Date: <u>MAY 13, 1994</u>
---------------------------------------	---------------------------

**EHC**ENVIRONMENTAL HAZARDS  
CONSULTING INC.**ACM ASSESSMENT FORM**Project No. E811/ - / - /05BClient: PENN MANOR SCH. DISTRICT

clnt div fac proj

Homog Area: 02Building: FRED S. EISELMAN ELEMENTARYNo. 04Assessment: AFunctional Space(s): BOILER ROOMMaterial: PIPE & FITTING INSULATION

FITTINGS

Amount: Sq.Ft. 90 Lm<sup>2</sup>Friability:  Friable  Non-FriableType:  Surfacing Thermal Insulation Misc.Asbestos Content: 15% C, 30% A**EXISTING DAMAGE**Rating:  Significantly Damaged  Damaged  No Damage

Physical Damage:

 Significant >10% Damaged <10% No Damage

Water Damage:

 Significant >10% Damaged <10% No Damage

Deterioration:

 Significant >10% Deteriorated <10% No Deterioration

Damage Extent:

 Localized Distributed BothRemarks: NO DAMAGE**DAMAGE POTENTIAL**Rating:  Significant Potential  Potential  Low PotentialFiber Release Deterrent:  None  Sealed Enclosure  Barrier  EncapsulantDescription: CUPPED & PAINTEDAccessibility:  Within Normal Reach  Barely Reachable  Not ReachableFunctional Space Activity: BOILER ROOMProximity To Items Requiring Maintenance/Repair: -0- FeetType Of Maintenance/Repair: PIPE REPAIR/MAINT.Subject To Moisture Damage:  Yes  NoSource:  Piping Roof Leak Sprinkler OtherDescription: NO LEAKS NOTED.Ventilation:  Yes  Mechanical  IntakeMovements:  High Moderate No Natural Exhaust Low VariableDescription: NATURAL AIR MOVEMENTPotential For Air Erosion:  High  Moderate  LowVibration - Potential For Fiber Release:  High  Moderate  LowDescription: NO VIBRATION NOTED.**EXPOSURE POTENTIAL**Rating:  Significant Potential  Potential  Low PotentialAccessibility:  General Population  Tenants  Operations Routine Maintenance RepairRemarks: AREA ACCESSED FOR MAINT/REPAIR ONLY.Dust/Debris Present:  Significant  Moderate  Slight  NoneFiber Transport:  None  Air Plenum/Chase  Ductwork  Mechanical Shaft  Elevator/Dumbwaiter  OtherDescription: NONEPhotographs:  Yes  No No's: \_\_\_\_\_AHERA Classification Number: 5ASSESSMENT: 122 RESPONSE: RO PRIORITY: PO PERIODIC SURVEILLANCE: SI O&H: IFA/MN: \_\_\_\_\_/CP: \_\_\_\_\_Inspector: KENNETH C. HausemanCertification No.: 93-11-12-23Signature: Kenneth C. HausemanDate: MAY 13, 1994

Project No. <u>E87111-1-105B</u>	Client: <u>Penn Manor School District</u>	Homog Area: <u>02</u>
clnt div fac proj	building: <u>Fred S. Eshelman Elementary</u>	No. <u>04</u>
		Assessment: <u>B</u>
Functional Space(s): <u>Original (1958) building, above suspended ceiling</u>		
Material: <u>Pipe fitting insulation</u>	Amount: <u>Sq.Ft. 156</u>	<u>in ft. Fittings</u>
Friability: <input checked="" type="checkbox"/> Friable <input type="checkbox"/> Non-Friable	Type: <input type="checkbox"/> Surfacing <input type="checkbox"/> Thermal Insulation <input type="checkbox"/> Misc.	Asbestos Content: <u>15% C, 30% A</u>

**EXISTING DAMAGE**Rating:  Significantly Damaged  Damaged  No Damage

## Physical Damage:

 Significant >10% Damaged <10% No Damage

## Water Damage:

 Significant >10% Damaged <10% No Damage

## Deterioration:

 Significant >10% Deteriorated <10% No Deterioration

## Damage Extent:

 Localized Distributed Both

Remarks:

**DAMAGE POTENTIAL**Rating:  Significant Potential  Potential  Low PotentialFiber Release Deterrent:  None  Sealed Enclosure  Barrier  EncapsulantDescription: wrapped, paintedAccessibility:  Within Normal Reach  Barely Reachable  Not ReachableFunctional Space Activity: above suspended ceilingProximity To Items Requiring Maintenance/Repair: < 7 FeetType Of Maintenance/Repair: pipesSubject To Moisture Damage:  Yes  NoSource:  Piping  Roof Leak  Sprinkler  Other

Description:

Ventilation:  Yes  Mechanical  Intake Movement:  High  Moderate No Natural Exhaust Low VariableDescription: intake intakes at ends of hallPotential For Air Erosion:  High  Moderate  LowVibration - Potential For Fiber Release:  High  Moderate  Low

Description:

**EXPOSURE POTENTIAL**Rating:  Significant Potential  Potential  Low PotentialAccessibility:  General Population  Tenants  Operations  Routine Maintenance  Repair

Remarks:

Dust/Debris Present:  Significant  Moderate  Slight  NoneFiber Transport:  None  Air Plenum/Chase  Ductwork  Mechanical Shaft  Elevator/Dumbwaiter  Other

Description:

Photographs:  Yes  No Nos: \_\_\_\_\_ AHERA Classification Number: \_\_\_\_\_ASSESSMENT: 1221 RESPONSE: RO PRIORITY: PO PERIODIC SURVEILLANCE: 51 O&H: INA/MN: /OP:Inspector: Don Farrell IICertification No.: PA 002277Signature: Don Farrell IIDate: 11-21-94

Object No <u>E87111-1-105B</u>	Client: <u>Penn Manor School District</u>	Homog Area: <u>02</u>
clnt div fac proj		
Building: <u>Fred S. Eshelman Elementary</u>	No. <u>07</u>	Assessment: <u>C</u>
Functional Space(s): <u>Kitchen (near serving line) space heater</u>		
Material: <u>Pipe fitting insulation</u>	Amount: _____	Sq.Ft. <u>4 fittings</u>
Friability: <input type="radio"/> Friable <input checked="" type="checkbox"/> Non-Friable	Type: <input type="radio"/> Surfacing <input checked="" type="checkbox"/> Thermal Insulation <input type="radio"/> Misc.	Asbestos Content: <u>15%C, 30%AF</u>

**EXISTING DAMAGE**Rating:  Significantly Damaged  Damaged  No Damage

Physical Damage:	Water Damage:	Deterioration:	Damage Extent:
<input type="radio"/> Significant >10%	<input type="radio"/> Significant >10%	<input type="radio"/> Significant >10%	<input type="radio"/> Localized
<input type="radio"/> Damaged <10%	<input type="radio"/> Damaged <10%	<input type="radio"/> Deteriorated <10%	<input type="radio"/> Distributed
<input checked="" type="checkbox"/> No Damage	<input checked="" type="checkbox"/> No Damage	<input checked="" type="checkbox"/> No Deterioration	<input type="radio"/> Both
Remarks:			

**DAMAGE POTENTIAL**Rating:  Significant Potential  Potential  Low Potential

Fiber Release Deterrent: <input type="radio"/> None <input type="radio"/> Sealed Enclosure	<input checked="" type="checkbox"/> Barrier	<input type="radio"/> Encapsulant
Description: <u>wrapped and painted</u>		
Accessibility: <input checked="" type="checkbox"/> Within Normal Reach <input type="radio"/> Barely Reachable <input type="radio"/> Not Reachable		
Functional Space Activity: <u>Food preparation</u>		
Proximity To Items Requiring Maintenance/Repair: <u>&lt; 1</u> Feet		
Type Of Maintenance/Repair: <u>pipes + heater</u>		
Subject To Moisture Damage: <input checked="" type="checkbox"/> Yes <input type="radio"/> No		
Description: <u>may be affected in future by kitchen cooking steam</u>		

Ventilation: <input checked="" type="checkbox"/> Yes	<input type="radio"/> Mechanical	<input type="radio"/> Intake	Movement: <input type="radio"/> High	<input type="radio"/> Moderate
<input type="radio"/> No	<input checked="" type="checkbox"/> Natural	<input type="radio"/> Exhaust	<input type="radio"/> Low	<input checked="" type="checkbox"/> Variable
Description:				
Potential For Air Erosion: <input type="radio"/> High <input type="radio"/> Moderate <input checked="" type="checkbox"/> Low				
Vibration - Potential For Fiber Release: <input type="radio"/> High <input type="radio"/> Moderate <input checked="" type="checkbox"/> Low				
Description:				

**EXPOSURE POTENTIAL**Rating:  Significant Potential  Potential  Low Potential

Accessibility: <input type="radio"/> General Population	<input checked="" type="checkbox"/> Tenants	<input checked="" type="checkbox"/> Operations	<input checked="" type="checkbox"/> Routine Maintenance	<input checked="" type="checkbox"/> Repair
Remarks: <u>reachable to adults in kitchen</u>				
Dust/Debris Present: <input type="radio"/> Significant <input type="radio"/> Moderate <input type="radio"/> Slight <input checked="" type="checkbox"/> None				
Fiber Transport: <input type="radio"/> None <input type="radio"/> Air Plenum/Chase <input type="radio"/> Ductwork <input type="radio"/> Mechanical Shaft <input type="radio"/> Elevator/Dumbwaiter <input checked="" type="checkbox"/> Other				
Description: <u>may pose danger to food intake (if damaged)</u>				

Photographs: <input type="radio"/> Yes	<input checked="" type="checkbox"/> No	No's: _____	AHERA Classification Number: <u>5</u>
ASSESSMENT: <u>123</u>	RESPONSE: <u>P22</u>	PRIORITY: <u>P2</u>	PERIODIC SURVEILLANCE: <u>52</u>
Q&M: <u>INA/MN</u>	OP: <u>PA</u>		
Inspector: <u>Don Farrell II</u>		Certification No.: <u>PA 002247</u>	
Signature: <u>Don Farrell II</u>		Date: <u>11-21-94</u>	

**EHC**ENVIRONMENTAL HAZARDS  
CONSULTING INC.**ACM ASSESSMENT FORM**Project No. EGII/ - / - /05BClient: PENN MANOR SCH. DISTRICT.Homog Area: 03

clnt div fac proj

Building: FRED S. ESHLEMAN ELEMENTARY.No. 04Assessment: AFunctional Space(s): BOILER ROOM.Material: EMERGENCY GENERATOR EXHAUST PIPE (TRANSITE) Amount:    Sq.Ft. 28 Lin.Ft.Friability:  Friable  Non-FriableType:  Surfacing  Thermal Insulation Misc.Asbestos Content: 20% C, 30% CRCC**EXISTING DAMAGE**Rating:  Significantly Damaged  Damaged  No Damage

Physical Damage:

 Significant >10% Damaged <10% No Damage

Water Damage:

 Significant >10% Damaged <10% No Damage

Deterioration:

 Significant >10% Deteriorated <10% No Deterioration

Damage Extent:

 Localized Distributed BothRemarks: NO DAMAGE.**DAMAGE POTENTIAL**Rating:  Significant Potential  Potential  Low PotentialFiber Release Deterrent:  None  Sealed Enclosure  Barrier  EncapsulantDescription: NONE.Accessibility:  Within Normal Reach  Barely Reachable  Not ReachableFunctional Space Activity: BOILER ROOM.Proximity To Items Requiring Maintenance/Repair: -0- FeetType Of Maintenance/Repair: EMER. GEN. EXHAUST REPAIRSubject To Moisture Damage:  Yes  NoSource:  Piping  Roof Leak  Sprinkler  OtherDescription: NO LEAKS NOTED.Ventilation:  Yes  Mechanical  IntakeMovement:  High  Moderate No Natural Exhaust Low VariableDescription: NATURAL AIR MOVEMENT.Potential For Air Erosion:  High  Moderate  LowVibration - Potential For Fiber Release:  High  Moderate  LowDescription: SIGNIFICANT VIBRATION AFFECTING NON-FRIABLE ACM.**EXPOSURE POTENTIAL**Rating:  Significant Potential  Potential  Low PotentialAccessibility:  General Population  Tenants  Operations  Routine Maintenance  RepairRemarks: AREA ACCESSED FOR MAINT/REPAIR ONLY.Dust/Debris Present:  Significant  Moderate  Slight  NoneFiber Transport:  None  Air Plenum/Chase  Ductwork  Mechanical Shaft  Elevator/Dumbwaiter  OtherDescription: NONE.Photographs:  Yes  No No's: \_\_\_\_\_AHERA Classification Number: BASSESSMENT: 122 RESPONSE: Bo PRIORITY: PO PERIODIC SURVEILLANCE: SI C&H: 3N MN:    CP:   Inspector: KENNETH W. Hauseman Certification No.: 93-11-12-23Signature: Kenneth W. Hauseman Date: MAY 13, 1994

**EHC**ENVIRONMENTAL HAZARDS  
CONSULTING INC.**ACM ASSESSMENT FORM**Project No. ESW 11-1-05BClient: PENN MANOR SCH. DISTRICTHomog Area: 04

clnt div fac proj

Building: FRED S. ESHUELMAN ELEMENTARYNo. 04Assessment: AFunctional Space(s): CLASSROOMSMaterial: 9"x9" FLOOR TILEAmount: 10,000 Sq.Ft. \_\_\_\_\_ Lin.Ft.Friability:  Friable  Non-FriableType:  Surfacing Thermal Insulation Misc. Asbestos Content:5%**EXISTING DAMAGE**Rating:  Significantly Damaged  Damaged  No Damage

Physical Damage:

 Significant >10% Damaged <10% No Damage

Water Damage:

 Significant >10% Damaged <10% No Damage

Deterioration:

 Significant >10% Deteriorated <10% No Deterioration

Damage Extent:

 Localized Distributed BothRemarks: NO DAMAGE**DAMAGE POTENTIAL**Rating:  Significant Potential  Potential  Low PotentialFiber Release Deterrent:  None  Sealed Enclosure  Barrier  EncapsulantDescription: WAXEDAccessibility:  Within Normal Reach  Barely Reachable  Not ReachableFunctional Space Activity: CLASSROOMSProximity To Items Requiring Maintenance/Repair: -0- FeetType Of Maintenance/Repair: FLOOR MAINT/REPAIRSubject To Moisture Damage:  Yes  NoSource:  Piping Roof Leak Sprinkler OtherDescription: NO LEAKS NOTEDVentilation:  Yes  Mechanical  Intake No Natural ExhaustMovement:  High Moderate Low VariableDescription: NATURAL AIR MOVEMENTPotential For Air Erosion:  High  Moderate  LowVibration - Potential For Fiber Release:  High  Moderate  LowDescription: NO VIBRATION NOTED**EXPOSURE POTENTIAL**Rating:  Significant Potential  Potential  Low PotentialAccessibility:  General Population  Tenants  Operations  Routine Maintenance  RepairRemarks: AREAS ACCESSIBLE TO ALL PERSONSDust/Debris Present:  Significant  Moderate  slight  NoneFiber Transport:  None  Air Plenum/Chase  Ductwork  Mechanical Shaft  Elevator/Dumbwaiter  OtherDescription: NONEPhotographs:  Yes  No No's: \_\_\_\_\_AHERA Classification Number: 8ASSESSMENT: A3 RESPONSE: PO PRIORITY: PO PERIODIC SURVEILLANCE: SI C&H: BNT/MN /CP: \_\_\_\_\_Inspector: KENNETH W. HausemanCertification No.: 93-11-12-23Signature: Kenneth W. HausemanDate: MAY 13, 1994

**EHC**ENVIRONMENTAL HAZARDS  
CONSULTING INC.**ACM ASSESSMENT FORM**Project No. E8111-1-05BClient: PENN MANOR SCH. DISTRICT

clnt div fac proj

Homog Area: 05Building: FRED S. ESHELMAN ELEMENTARYNo. 04Assessment: AFunctional Space(s): EXTERIOR SOFFITS.Material: TRANSITE PANELS.Amount: 3000 Sq.Ft.

Lin.Ft.

Friability:  Friable  Non-FriableType:  Surfacing  Thermal Insulation Misc.Asbestos Content: Assumed**EXISTING DAMAGE**Rating:  Significantly Damaged  Damaged  No Damage

Physical Damage:

Water Damage:

Deterioration:

Damage Extent:

 Significant >10% Significant >10% Significant >10% Localized Damaged <10% Damaged <10% Deteriorated <10% Distributed No Damage No Damage No Deterioration BothRemarks: NO DAMAGE**DAMAGE POTENTIAL**Rating:  Significant Potential  Potential  Low PotentialFiber Release Deterrent:  None  Sealed Enclosure  Barrier  EncapsulantDescription: PAINTED.Accessibility:  Within Normal Reach  Barely Reachable  Not ReachableFunctional Space Activity: EXTERIOR SOFFITS.Proximity To Items Requiring Maintenance/Repair: -0' FeetType Of Maintenance/Repair: ROOFING REPAIRSubject To Moisture Damage:  Yes  NoSource:  Piping  Roof Leak  Sprinkler  OtherDescription: NO LEAKS NOTEDVentilation:  Yes Mechanical IntakeMovement:  High Moderate No Natural Exhaust Low VariableDescription: WIND.Potential For Air Erosion:  High  Moderate  LowVibration - Potential For Fiber Release:  High  Moderate  LowDescription: NO VIBRATION NOTED.**EXPOSURE POTENTIAL**Rating:  Significant Potential  Potential  Low PotentialAccessibility:  General Population  Tenants  Operations  Routine Maintenance  RepairRemarks: AREAS ACCESSIBLE TO ALL PERSONS.Dust/Debris Present:  Significant  Moderate  Slight  NoneFiber Transport:  None  Air Plenum/Chase  Ductwork  Mechanical Shaft  Elevator/Dumbwaiter  OtherDescription: NONEPhotographs:  Yes  No No's: \_\_\_\_\_AHERA Classification Number: BASSESSMENT: 123 / RESPONSE: Ro PRIORITY: PO PERIODIC SURVEILLANCE: SI CMH: 3N / MN: /CP /Inspector: KENNETH W. HAUSERMAN Certification No.: 93-11-12-23Signature: Kenneth W. HausermanDate: MAY 13, 1994

Project No: <u>87111.00100.105B</u>	client: <u>Penn Manor School District</u>	Homog Area: <u>26</u>
clnt div fac proj		
Building: <u>Fred S. Eshelman Elementary</u>	No. <u>07</u>	Assessment: <u>A</u>
Functional Space(s): <u>Corridors throughout building</u>		
Material: <u>Pink terrazo flooring</u>	Amount: <u>3,000</u> Sq.Ft.	Lin.Ft.
Friability: <input type="radio"/> Friable <input checked="" type="checkbox"/> Non-Friable	Type: <input type="radio"/> Surfacing <input type="radio"/> Thermal Insulation <input checked="" type="checkbox"/> Misc.	Asbestos Content: <u>Assumed</u>

### EXISTING DAMAGE

Rating:  Significantly Damaged  Damaged  No Damage

Physical Damage:	Water Damage:	Deterioration:	Damage Extent:
<input type="radio"/> Significant >10%	<input type="radio"/> Significant >10%	<input type="radio"/> Significant >10%	<input type="radio"/> Localized
<input type="radio"/> Damaged <10%	<input type="radio"/> Damaged <10%	<input type="radio"/> Deteriorated <10%	<input type="radio"/> Distributed
<input checked="" type="checkbox"/> No Damage	<input checked="" type="checkbox"/> No Damage	<input checked="" type="checkbox"/> No Deterioration	<input type="radio"/> Both
Remarks: _____			

### DAMAGE POTENTIAL

Rating:  Significant Potential  Potential  Low Potential

Fiber Release Deterrent:	<input type="radio"/> None <input type="radio"/> Sealed Enclosure <input type="radio"/> Barrier <input checked="" type="checkbox"/> Encapsulant
Description: <u>Waxed</u>	
Accessibility:	<input checked="" type="checkbox"/> Within Normal Reach <input type="radio"/> Barely Reachable <input type="radio"/> Not Reachable
Functional Space Activity:	
Proximity To Items Requiring Maintenance/Repair:	<u>&lt;1</u> Feet
Type Of Maintenance/Repair:	<u>floors</u>

Subject To Moisture Damage:	<input type="radio"/> Yes <input checked="" type="checkbox"/> No	Sources:	<input type="radio"/> Piping <input type="radio"/> Roof Leak <input type="radio"/> Sprinkler <input type="radio"/> Other	
Description:				
Ventilation:	<input checked="" type="checkbox"/> Yes <input type="radio"/> No	<input type="radio"/> Mechanical <input type="radio"/> Intake	Movement:	<input type="radio"/> High <input type="radio"/> Moderate
		<input checked="" type="checkbox"/> Natural <input type="radio"/> Exhaust		<input type="radio"/> Low <input checked="" type="checkbox"/> Variable
Description:	<u>movement of bldg. occupants</u>			
Potential For Air Erosion:	<input type="radio"/> High <input type="radio"/> Moderate <input checked="" type="checkbox"/> Low			

Vibration - Potential For Fiber Release:	<input type="radio"/> High <input type="radio"/> Moderate <input checked="" type="checkbox"/> Low
Description:	

### EXPOSURE POTENTIAL

Rating:  Significant Potential  Potential  Low Potential

Accessibility:	<input checked="" type="checkbox"/> General Population <input checked="" type="checkbox"/> Tenants <input checked="" type="checkbox"/> Operations <input checked="" type="checkbox"/> Routine Maintenance <input checked="" type="checkbox"/> Repair
Remarks:	
Dust/Debris Present:	<input type="radio"/> Significant <input type="radio"/> Moderate <input type="radio"/> Slight <input checked="" type="checkbox"/> None
Fiber Transport:	<input checked="" type="checkbox"/> None <input type="radio"/> Air Plenum/Chase <input type="radio"/> Ductwork <input type="radio"/> Mechanical Shaft <input type="radio"/> Elevator/Dumbwaiter <input type="radio"/> Other
Description:	

Photographs: <input type="radio"/> Yes <input checked="" type="checkbox"/> No	No's: _____	AHERA Classification Number: <u>8</u>		
ASSESSMENT: <u>1/3/1</u>	RESPONSE: <u>RPP</u>	PRIORITY: <u>P1</u>	PERIODIC SURVEILLANCE: <u>SL</u>	O&M: <u>3NT/MN: / /OP:</u>
Inspector: <u>Don Farrell II</u>	Certification No.: <u>PA 002247</u>			
Signature: <u>Don Farrell II</u>	Date: <u>11-21-94</u>			

## RESPONSE ACTIONS RECOMMENDED

The recommended response actions contained on the following pages are proposed by the Management Planner as the least burdensome method in regard to short term costs sufficient to protect human health and the environment. The recommendations were based, in general on the guidelines included in Section 763.90 of 40 CFR Part 763 Subpart Eg. (AHERA Regulations).

These recommended response actions should be considered along with concerns for local circumstances, occupancy and use patterns within the building, renovation/addition/demolition plans for the building, and long-term costs. The School District should then select response actions which are at least equal to the recommended response actions in regard to their adequacy to protect human health and the environment.

Priorities for performance of the recommended response actions are defined as follows:

- |           |   |
|-----------|---|
| Immediate | the hazard is such in terms of both damage and exposure potential to warrant isolation of the area until abatement can be performed.  |
| High      | due to damage and a significant potential for exposure, abatement should be performed as soon as possible.  |
| Medium    | due to limited damage or a low frequency of use of these areas by a limited number of personnel, the hazard is such that abatement can take place as part of the normal maintenance and repair cycle of the facility. An operations and maintenance program, including periodic monitoring, should be maintained.   |
| Low       | these areas have minimal damage potential during normal activities. In many cases the ACBM is non-friable, relatively inaccessible, or otherwise protected so that fiber release is very unlikely. Periodic monitoring of these areas should continue to ensure that no change in the condition of the ACM takes place. An operations and maintenance program should be maintained. |

008711 Penn Manor School District  
BLDG. NO: 04 BUILDING NAME: Fred S. Eshelman Elem. School

**RECOMMENDED RESPONSE ACTIONS**

Home.	Area Asmt' No.	Functional Space(s)	Material	Recommended Response Action	Priority of Response	Recommended Periodic Surveillance
01	A	Boiler Room	Breeching Insulation	R11 Repair damaged material	P2 Medium	\$1 Semi-Annual
02	A	Boiler Room	Pipe Fitting Insulation	RO None	P0 None	\$1 Semi-Annual
02	B	Orig. (1958) Entire Building, Above Suspended Ceilings	Pipe Fitting Insulation	RO None	P0 None	\$1 semi-Annual

**REASON FOR RECOMMENDATION:**

222 Material is Friable, has Damage, Potential for damage, and Potential for exposure.

**REASON FOR RECOMMENDATION:**

122 Material is Friable, has No Damage, Potential for damage, and Potential for exposure.

**REASON FOR RECOMMENDATION:**

122 Material is Friable, has No Damage, Potential for damage, and Potential for exposure.

BLDG. NO: 04 BUILDING NAME: Fred S. Eshelman Elem. School

RECOMMENDED RESPONSE ACTIONS [CONTINUED]

Home.	Area No.	Ass'n't.	Functional Space(s)	Material	Recommended Response Action	Priority of Response	Recommended Periodic Surveillance
02	C	Kitchen (Near Serving Line) Space Heater	Pipe Fitting Insulation	R0 None	P0 None	P0 None	\$1 Semi-Annual

REASON FOR RECOMMENDATION:

- 123 Material is Friable, has No Damage, Potential for damage, and Significant Potential for exposure.

03	A	Boiler Room	Emergency Generator Exhaust Pipe (Transite)	R0 None	P0 None	P0 None	\$1 Semi-Annual
----	---	-------------	---	---------	---------	---------	-----------------

REASON FOR RECOMMENDATION:

- 122 Material is Non-Friable, has No Damage, Potential for damage, and Potential for exposure.

04	A	Classrooms	9"x9" Floor Tile	R0 None	P0 None	P0 None	\$1 Semi-Annual
----	---	------------	------------------	---------	---------	---------	-----------------

REASON FOR RECOMMENDATION:

- 123 Material is Non-Friable, has No Damage, Potential for damage, and Significant Potential for exposure.

008711 Penn Manor School District

BLDG. NO: 04 BUILDING NAME: Fred S. Eshelman Elemp. School

**RECOMMENDED RESPONSE ACTIONS**

Home.	Area	Asmt	Functional Space(s)	Material	Recommended Response Action	Priority of Response	Recommended Periodic Surveillance
No.	No.	No.					
05	A	Exterior Soffits	Transite Boards	R0 None	P0 None	S1 Semi-Annual	
<b>REASON FOR RECOMMENDATION:</b>							
123 Material is Non-Friable, has No Damage, Potential for damage, and Significant Potential for exposure.							
06	A	Corridors Throughout Building	Pink Terrazzo Flooring	R99 Sample material to confirm asbestos content	P1 Low	S1 Semi-Annual	
<b>REASON FOR RECOMMENDATION:</b>							
113 Material is Non-Friable, has No Damage, Low Potential for damage, and Significant Potential for exposure.							

BLDG. NO: 79 BUILDING NAME: Fred S. Eshelman Elem. School

## SELECTED RESPONSE ACTIONS

Home.		Area No.	Asmt No.	Functional Space(s)	Material	Selected Response Action	Schedule for Response
01	A			Boiler Room	Breeching Insulation	R11 Repair damaged material	August, 1994

## REASON FOR RECOMMENDATION:

222 Material is Friable, has Damage, Potential for damage, and Potential for exposure.

02	A	Boiler Room	Pipe Fitting Insulation	R0 None
----	---	-------------	----------------------------	---------

## REASON FOR RECOMMENDATION:

122 Material is Friable, has No Damage, Potential for damage, and Potential for exposure.

02	B	Orig. (1958) Entire Building, Above Suspended Ceilings	Pipe Fitting Insulation	R0 None
----	---	--	----------------------------	---------

## REASON FOR RECOMMENDATION:

123 Material is Friable, has No Damage, Potential for damage, and Significant Potential for exposure.

02	C	Kitchen (Near Serving Line) Space Heater	Pipe Fitting Insulation	R0 None
----	---	--	----------------------------	---------

## REASON FOR RECOMMENDATION:

123 Material is Friable, has No Damage, Potential for damage, and Significant Potential for exposure.

BLDG. NO: 79 BUILDING NAME: Fred S. Eshelman Elem. School

## SELECTED RESPONSE ACTIONS

Homo.		Area No.	Asmt No.	Functional Space(s)	Material	Selected Response Action	Schedule for Response
03	A			Boiler Room	Emergency Generator Exhaust Pipe (Transite)	R0 None	-

## REASON FOR RECOMMENDATION:

122 Material is Non-Friable, has No Damage, Potential for damage, and Potential for exposure.

04	A	Classrooms	9"x9" Floor Tile	R0 None
----	---	------------	------------------	---------

## REASON FOR RECOMMENDATION:

123 Material is Non-Friable, has No Damage, Potential for damage, and Significant Potential for exposure.

05	A	Exterior Soffits	Transite Boards	R0 None
----	---	------------------	-----------------	---------

## REASON FOR RECOMMENDATION:

123 Material is Non-Friable, has No Damage, Potential for damage, and Significant Potential for exposure.

06	A	Corridors Throughout Building	Pink Terrazzo Flooring	R99 Sample material to confirm asbestos content
----	---	-------------------------------	------------------------	---

## REASON FOR RECOMMENDATION:

113 Material is Non-Friable, has No Damage, Low Potential for damage, and Significant Potential for exposure.

BLDG. NO: 04 BUILDING NAME: Fred S. Eshelman Elem. School

LIST OF ASBESTOS-CONTAINING MATERIALS

ASBESTOS CONTENT: C - Chrysotile, A - Amosite, CR - Crocidolite, TR - Tremolite, AC - Actinolite  
ASMD - Assumed, ND - None Detected

Homo. Area No.	Assm't. No.	Functional Space(s)	Material	Approx. Amount	Asbestos Content
01	A	Boiler Room	Breeching Insulation	280 S.F.	55% C *
02	A	Boiler Room	Pipe Fitting Insulation	90 Fittings	15% C * 30% A
02	B	Orig. (1958) Entire Building, Above Suspended Ceilings	Pipe Fitting Insulation	156 Fittings	15% C * 30% A
02	C	Kitchen (Near Serving Line) Space Heater	Pipe Fitting Insulation	4 Fittings	15% C * 30% A
03	A	Boiler Room	Emergency Generator Exhaust Pipe (Transite)	28 L.F.	20% C * 30% CR
04	A	Classrooms	9"x9" Floor Tile	15,000 S.F.	5% C *
05	A	Exterior Soffits	Transite Boards	3,000 S.F.	ASMD *
06	A	Corridors Throughout Building	Pink Terrazzo Flooring	3,000 S.F.	ASMD

Sampled/Assumed by others.

BLDG. NO: 79 BUILDING NAME: Fred S. Eshelman Elem. School

## PERIODIC SURVEILLANCE SCHEDULE

Homo.

Area

Assm't.

No.

No.

Functional Space(s)

Material

Surveillance  
Schedule

01	A	Boiler Room	Breeching Insulation	S1	Semi-Annual
02	A	Boiler Room	Pipe Fitting Insulation	S1	Semi-Annual
02	B	Orig. (1958) Entire Building, Above Suspended Ceilings	Pipe Fitting Insulation	S1	Semi-Annual
02	C	Kitchen (Near Serving Line) Space Heater	Pipe Fitting Insulation	S1	Semi-Annual
03	A	Boiler Room	Emergency Generator Exhaust Pipe (Transite)	S1	Semi-Annual
04	A	Classrooms	9"x9" Floor Tile	S1	Semi-Annual
05	A	Exterior Soffits	Transite Boards	S1	Semi-Annual
06	A	Corridors Throughout Building	Pink Terrazzo Flooring	S1	Semi-Annual

00871 Penn Manor School District

BLDG. NO: 04 BUILDING NAME: Fred S. Eshelman Elem. School

## OPERATIONS &amp; MAINTENANCE PROCEDURES

Home Area No.	Assmt'nt No.	Functional Space	Material	Applicable Operations & Maintenance Procedures						
				Code	Monitoring	Cleaning	Operational	Protection	Maintenance	Post-Activity
01	A	Boiler Room	Breeching Insulation	1F	-	H,I	-	A,B	N,P,Q,S,V	X,Y,Z
02	A	Boiler Room	Pipe Fitting Insulation	1F	-	H,I	-	A,B	N,P,Q,S,V	X,Y,Z
02	B	Orig. (1958) Entire Building, Above Suspended Ceilings	Pipe Fitting Insulation	1NA	-	-	-	A,B	N,Q,S,U,V	X,Y,Z
02	C	Kitchen (Near Serving Line) Space Heater	Pipe Fitting Insulation	1NA	-	-	-	A,B	N,Q,S,U,V	X,Y,Z
03	A	Boiler Room	Emergency Generator Exhaust Pipe (Transite)	3N	-	-	-	A,B	N,Q,R,T,V	X,Y,Z
04	A	Classrooms	9"x9" Floor Tile	3NT	-	-	-	A,B	N,Q,R,T,V	X,Y,Z
05	A	Exterior Soffits	Transite Boards	3N	-	-	-	A,B	N,Q,R,V	X,Y,Z

008711

Penn Manor School District

BLDG. NO: 04

BUILDING NAME: Fred S. Eshelman Elem. School

**OPERATIONS & MAINTENANCE PROCEDURES (CONTINUED)**

Home Area No.	Ass'n't No.	Functional Space	Material	Applicable Operations & Maintenance Procedures					
				Code	Monitoring	Cleaning	Operational	Protection	Maintenance
06 A	Corridors Throughout Building	Pink Terrazzo Flooring	ZNT				A,B	N,Q,R,T,V	X,Y,Z

BLDG. NO: 04

BUILDING NAME: Fred S. Eshelman Elec. School

**RECOMMENDED RESPONSE ACTION / REMOVAL COST ESTIMATES**

Hono.	Area No.	Asm't No.	Functional Space(s)	Material	Recommended Response Action	Priority of Response	Response Action Cost Estimate	Removal Cost Estimate
01	A		Boiler Room	Breeching Insulation material	R11 Repair damaged material	P2 Medium	\$1,000.00	\$0.00

**TOTAL ESTIMATED RECOMMENDED RESPONSE ACTION COST FOR BUILDING:**

**\$1,000.00**

**TOTAL ESTIMATED REMOVAL COST FOR BUILDING:**

**\$0.00**

008711

BLDG. NO: 79 BUILDING NAME: Fred S. Eshelman Elem. School

**SELECTED RESPONSE ACTION COST ESTIMATES**

Home - Area No.	Asmt No.	Functional Space(s)	Material	Selected Response Action	Schedule for Response	Estimated Cost
01	A	Boiler Room	Breeching Insulation	R11 Repair damaged material	August, 1994	\$1,000.00

**TOTAL ESTIMATED SELECTED RESPONSE ACTION COST ESTIMATE FOR BUILDING:**

**\$1,000.00**